

**Exhibit 20 to Plaintiff's  
Supplemental Opposition to  
Defendant Benton Express, Inc.'s  
Motion for Summary Judgment**

AST-27  
REV. 1/01

## ALABAMA UNIFORM TRAFFIC ACCIDENT REPORT

DPS

Accident No

3398

Shaded Areas To Be Used By Data Processing Only		Event #		Sheet		Microfilm No.		Local Case No.	
2005-00070121		1 of 5						3398	
Date		Time		County		City		Highway Classification	
04/11/2005		06:05		03		Montgomery		D-Interstate S-State F-Federal C-County P-Private Prop. O-Other	
Month Day Year		AM PM		Day of Week		City		Local Zone	
04 11 2005		06:05		T W TH		Montgomery		01	
On Street Road or Highway		At Intersection of or Between (Node 1)		And (Node 2)					
Interstate 85 S		Interstate 65 S		Interstate 85 N Ent Ramp					
Street or Road Code		Node Code		Node Code		Node Code			
2085		2614		2614		N/A			
Intersection Related		Mile Post		Control Access		1 Main Rd		5 Exit Ramp	
1 Node 1 2 Node 2		000.10		Hwy Loc		2 Frontage Rd 4 Entrance Ramp		6 N/A	
First Harmful Event		Event Location		Distance to Fixed Object		No. of Vehicles		No. of Pedestrians	
52		1		N/A FT		0		0	
Driver Full Name		Street Address		City and State		Zip		Telephone No	
Craig Anthony Stephens		1959 Stacey Road		Cantonment, FL		32533		(850) 937-8911	
D O B		Race Sex		DL State		Driver License No		DL Class	
11 02 1964		B M FL		FL		S 315 101 64 402 0		A C	
Place of Employment		Benton Express Inc.		Liability Insurance Co.		CNA Insurance		Social Security No	
11 02 1964		B M FL		FL		S 315 101 64 402 0		111-NA-111	
Driver Condition		1 - No Defect		3 - Fatigued		8 - Other		Officer's Opinion	
2 - Apparently Asleep		4 - III		9 - Unknown				Alcohol: Yes No	
01		Interstate 85		Road Code		2085		Travel Direction	
01		Interstate 85		Road Code		2085		Travel Direction	
Veh Year		Make		Model		Body		V.I.N.	
1998		Volvo		Ira		N/A		4VGDAPF8WN861468	
Owner's Name		Benton Express Inc.		Street or R.F.D.		2061 SCL Drive		City	
Benton Express Inc.		Benton Express Inc.		2061 SCL Drive		2061 SCL Drive		Jacksonville	
Type		Use		Hazardous Cargo		Attachment		Contributing Defect	
1 - Auto		1 - Personal		1 - None		1 - None		1 - None	
2 - Sta. Wagon		2 - Driver Trng.		2 - Explosive		2 - Mobile Home		2 - Brakes	
3 - Pick Up		3 - Construction		3 - Gas		3 - Semi Trailer		3 - Steering	
4 - Van		4 - Ambulance/Paramedical		4 - Flam/Combust Liq.		4 - Utility Trailer		4 - Power Plant	
5 - Truck Tractor		5 - Military		5 - Flammable Solids		5 - Wheel Trailer		5 - Suspension	
6 - Other Truck		6 - Tax		6 - Oxidizer/Peroxide		6 - Boat Trailer		6 - Tires	
7 - Comm Bus		7 - Transport Prop		7 - Poison		7 - Camper Trailer		7 - Exhaust	
8 - School Bus		8 - Agriculture		8 - Radioactive Material		8 - Towed Vehicle		8 - Lights	
9 - Other Bus		9 - Wrecker/Tow		9 - Corrosive Material		9 - Tanker		9 - Fuel System	
10 - Motorcycle				10 - Other		10 - Pole Trailer		10 - Windshield	
						11 - Double Trailer		11 - Restraint Sys.	
						12 - Truck		12 - Wheels	
						13 - Cargo		13 - Coupling	
						14 - Fuel System		14 - Tires	
						15 - Other		15 - Exhaust	
						16 - Other		16 - Lights	
						17 - Other		17 - Turn Signal	
						18 - Other		18 - Unknown	
						19 - Other		19 - Unknown	
						20 - Other		20 - Unknown	
						21 - Other		21 - Unknown	
						22 - Other		22 - Unknown	
						23 - Other		23 - Unknown	
						24 - Other		24 - Unknown	
						25 - Other		25 - Unknown	
						26 - Other		26 - Unknown	
						27 - Other		27 - Unknown	
						28 - Other		28 - Unknown	
						29 - Other		29 - Unknown	
						30 - Other		30 - Unknown	
						31 - Other		31 - Unknown	
						32 - Other		32 - Unknown	
						33 - Other		33 - Unknown	
						34 - Other		34 - Unknown	
						35 - Other		35 - Unknown	
						36 - Other		36 - Unknown	
						37 - Other		37 - Unknown	
						38 - Other		38 - Unknown	
						39 - Other		39 - Unknown	
						40 - Other		40 - Unknown	
						41 - Other		41 - Unknown	
						42 - Other		42 - Unknown	
						43 - Other		43 - Unknown	
						44 - Other		44 - Unknown	
						45 - Other		45 - Unknown	
						46 - Other		46 - Unknown	
						47 - Other		47 - Unknown	
						48 - Other		48 - Unknown	
						49 - Other		49 - Unknown	
						50 - Other		50 - Unknown	
						51 - Other		51 - Unknown	
						52 - Other		52 - Unknown	
						53 - Other		53 - Unknown	
						54 - Other		54 - Unknown	
						55 - Other		55 - Unknown	
						56 - Other		56 - Unknown	
						57 - Other		57 - Unknown	
						58 - Other		58 - Unknown	
						59 - Other		59 - Unknown	
						60 - Other		60 - Unknown	
						61 - Other		61 - Unknown	
						62 - Other		62 - Unknown	
						63 - Other		63 - Unknown	
						64 - Other		64 - Unknown	
						65 - Other		65 - Unknown	
						66 - Other		66 - Unknown	
						67 - Other		67 - Unknown	
						68 - Other		68 - Unknown	
						69 - Other		69 - Unknown	
						70 - Other		70 - Unknown	
						71 - Other		71 - Unknown	
						72 - Other		72 - Unknown	
						73 - Other		73 - Unknown	
						74 - Other		74 - Unknown	
						75 - Other		75 - Unknown	
						76 - Other		76 - Unknown	
						77 - Other		77 - Unknown	
						78 - Other		78 - Unknown	
						79 - Other		79 - Unknown	
						80 - Other		80 - Unknown	
						81 - Other		81 - Unknown	
						82 - Other		82 - Unknown	
						83 - Other		83 - Unknown	
						84 - Other		84 - Unknown	
						85 - Other		85 - Unknown	
						86 - Other		86 - Unknown	
						87 - Other		87 - Unknown	
						88 - Other		88 - Unknown	
						89 - Other		89 - Unknown	
						90 - Other		90 - Unknown	
						91 - Other		91 - Unknown	
						92 - Other		92 - Unknown	
						93 - Other		93 - Unknown	
						94 - Other		94 - Unknown	
						95 - Other		95 - Unknown	
						96 - Other		96 - Unknown	
						97 - Other		97 - Unknown	
						98 - Other		98 - Unknown	
						99 - Other		99 - Unknown	
						100 - Other		100 - Unknown	
						101 - Other		101 - Unknown	
						102 - Other		102 - Unknown	
						103 - Other		103 - Unknown	
						104 - Other		104 - Unknown	
						105 - Other		105 - Unknown	
						106 - Other		106 - Unknown	
						107 - Other		107 - Unknown	
						108 - Other		108 - Unknown	
						109 - Other		109 - Unknown	
						110 - Other		110 - Unknown	
						111 - Other		111 - Unknown	
						112 - Other		112 - Unknown	
						113 - Other		113 - Unknown	
						114 - Other		114 - Unknown	
						115 - Other		115 - Unknown	
						116 - Other		116 - Unknown	
						117 - Other		117 - Unknown	
						118 - Other		118 - Unknown	
						119 - Other		119 - Unknown	
						120 - Other		120 - Unknown	
						121 - Other		121 - Unknown	
						122 - Other		122 - Unknown	
						123 - Other		123 - Unknown	
						124 - Other		124 - Unknown	
						125 - Other		125 - Unknown	
						126 - Other		126 - Unknown	
						127 - Other		127 - Unknown	
						128 - Other		128 - Unknown	
						129 - Other		129 - Unknown	
						130 - Other		130 - Unknown	
						131 - Other		131 - Unknown	
						132 - Other		132 - Unknown	
						133 - Other		133 - Unknown	
						134 - Other		134 - Unknown	
						135 - Other		135 - Unknown	
						136 - Other		136 - Unknown	
						137 - Other		137 - Unknown	
						138 - Other		138 - Unknown	
						139 - Other		139 - Unknown	
						140 - Other		140 - Unknown	
						141 - Other		141 - Unknown	
						142 - Other		142 - Unknown	
						143 - Other		143 - Unknown	
						144 - Other		144 - Unknown	
						145 - Other		145 - Unknown	
						146 - Other		146 - Unknown	
						147 - Other		147 - Unknown	
						148 - Other		148 - Unknown	
						149 - Other		149 - Unknown	
						150 - Other		150 - Unknown	
						151 - Other		151 - Unknown	
						152 - Other		152 - Unknown	
						153 - Other		153 - Unknown	
						154 - Other		154 - Unknown	
						155 - Other		155 - Unknown	
						156 - Other		156 - Unknown	
						157 - Other		157 - Unknown	
						158 - Other		158 - Unknown	
						159 - Other		159 - Unknown	
						160 - Other		160 - Unknown	
						161 - Other		161 - Unknown	
						162 - Other		162 - Unknown	
						163 - Other		163 - Unknown	
						164 - Other		164 - Unknown	
						165 - Other		165 - Unknown	
						166 - Other		166 - Unknown	
						167 - Other		167 - Unknown	
						168 - Other		168 - Unknown	
						169 - Other		169 - Unknown	
						170 - Other		170 - Unknown	
						171 - Other			

SEATING		VICTIMS		N/A		CODES		NARRATIVE AND DIAGRAM																																																																																												
Unit 1	<table border="1"> <tr><td>1</td><td>22</td><td>3</td></tr> <tr><td>4</td><td>5</td><td>8</td></tr> <tr><td>7</td><td>6</td><td>9</td></tr> </table>	1	22	3	4	5	8	7	6	9	<table border="1"> <tr><td>10</td><td>11</td></tr> </table>	10	11	12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstances/ Codes Not Applicable Other Involved Safety Equipment: <input type="checkbox"/>	Unit 2	<table border="1"> <tr><td>42</td><td>5</td><td>6</td></tr> <tr><td>7</td><td>8</td><td>9</td></tr> </table>	42	5	6	7	8	9	<table border="1"> <tr><td>11</td></tr> </table>	11	14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstances/ Codes Not Applicable Other Involved Safety Equipment: <input type="checkbox"/>	<b>SAFETY EQUIPMENT</b> 01 - None Included 05 - Not Applicable 08 - Unknown (Any Type) Lap Belt Only 11 - Fastened 12 - Not Fastened Lap/Shoulder Harness 21 - Lap Only Used 22 - Neither Used 23 - Shoulder Only Used 24 - Both Used Motorcycle Helmet 31 - None Used 32 - Used <b>Air Bags</b> 41 - Deployed, Belts Used 42 - Not Deployed, Belts Used 43 - Deployed, Belts Not Used 44 - Not Deployed, Belts Not Used Child Restraint 51 - Child Restraint Used 52 - Other Restraint Used 53 - None Used Petal/Crystal Protection 61 - Contrasting Clothing 62 - Non-contrasting Clothing																																																																										
1	22	3																																																																																																		
4	5	8																																																																																																		
7	6	9																																																																																																		
10	11																																																																																																			
42	5	6																																																																																																		
7	8	9																																																																																																		
11																																																																																																				
Name: Craig Anthony Stephens		Address: 1959 Stacey Road, Cantonment FL 32533		Unit No: 1	Seat Pos: 1	Injury Type: K	Age: 41	Sex: M	Ejection: F	First Aid By: M																																																																																										
Taken To: City Morgue		Taken By: Montgomery Police Department Crime Scene Investigator																																																																																																		
Name: Ronald Tyrone Roby		Address: 4441 Sunnybrook Drive, Montgomery, AL 36108		Unit No: 2	Seat Pos: 1	Injury Type: K	Age: 44	Sex: M	Ejection: T	First Aid By: M																																																																																										
Taken To: City Morgue		Taken By: Montgomery Police Department Crime Scene Investigator																																																																																																		
Injury Type		Ejected		First Aid By		P - Police																																																																																														
K - Killed B - Bruise/Abrasion/Swelling		A - Visible or Carried Non Scene C - Not Visible - Has Pain/Faint		N - Not F - Fully P - Partially		T - Trapped U - Unknown A - Not Applicable		A - Ambulance Attended D - Doctor		M - Paramedic G - Other																																																																																										
SEE SHEETS 2-4 of 6																																																																																																				
Officer's Opinion of What Happened: Vehicle Number One (1) was traveling south on Interstate 85. A witness stated Vehicle Number One (1) had been driving erratically. Vehicle Number One (1) approached Interstate 85 south and the Day Street Exit and crashed into the guardrail cushion. Vehicle Number One (1) then traveled up onto the concrete guardrail, where it left the overpass and landed onto Interstate 65 South colliding with Vehicle Number Two (2) which was traveling south-bound in the right hand lane. Both vehicles came to an uncontrolled rest.																																																																																																				
<b>ROADWAY ENVIRONMENT</b> For Each Roadway Environment Field, Circle One Entry for Each Involved Unit <table border="1"> <thead> <tr> <th>Unit</th> <th>Contributing Road Defects</th> <th>Surface Construction</th> <th>Condition</th> <th>Accident In Or Related To Road Construction Zone?</th> <th>Material in Roadway (Contributing)</th> <th>Material Source</th> <th>Character</th> </tr> </thead> <tbody> <tr> <td>Unit 1</td> <td>1 - None 2 - Shoulders Low 3 - Shoulders High 4 - Holes, Bumps, Etc. 5 - Other</td> <td>1 - Asphalt 2 - Concrete 3 - Brick 4 - Unpaved 5 - Other</td> <td>1 - Dry 2 - Wet 3 - Ice 4 - Snowy/Slushy 5 - Muddy 6 - Other</td> <td>Yes Yes</td> <td>1 - None 2 - Rocks 3 - Trees/Limbs 4 - Dirt</td> <td>1 - Not Applicable 2 - Natural Environment 3 - Dropped From Vehicle 4 - Already in Road, But Fell From Vehicle 5 - Other 6 - Unknown</td> <td>1 - Straight-Level 2 - Straight-Down Grade 3 - Straight-Up Grade 4 - Straight-Hillcrest 5 - Curve-Level 6 - Curve-Down G 7 - Curve-Up Grad 8 - Curve-Hillcrest</td> </tr> <tr> <td>Unit 2</td> <td>1 - None 2 - Shoulders Low 3 - Shoulders High 4 - Holes, Bumps, Etc. 5 - Other</td> <td>1 - Asphalt 2 - Concrete 3 - Brick 4 - Unpaved 5 - Other</td> <td>1 - Dry 2 - Wet 3 - Ice 4 - Snowy/Slushy 5 - Muddy 6 - Other</td> <td>Yes Yes</td> <td>1 - None 2 - Rocks 3 - Trees/Limbs 4 - Dirt</td> <td>1 - Not Applicable 2 - Natural Environment 3 - Dropped From Vehicle 4 - Already in Road, But Fell From Vehicle 5 - Other 6 - Unknown</td> <td>1 - Straight-Level 2 - Straight-Down Grade 3 - Straight-Up Grade 4 - Straight-Hillcrest 5 - Curve-Level 6 - Curve-Down G 7 - Curve-Up Grad 8 - Curve-Hillcrest</td> </tr> </tbody> </table>											Unit	Contributing Road Defects	Surface Construction	Condition	Accident In Or Related To Road Construction Zone?	Material in Roadway (Contributing)	Material Source	Character	Unit 1	1 - None 2 - Shoulders Low 3 - Shoulders High 4 - Holes, Bumps, Etc. 5 - Other	1 - Asphalt 2 - Concrete 3 - Brick 4 - Unpaved 5 - Other	1 - Dry 2 - Wet 3 - Ice 4 - Snowy/Slushy 5 - Muddy 6 - Other	Yes Yes	1 - None 2 - Rocks 3 - Trees/Limbs 4 - Dirt	1 - Not Applicable 2 - Natural Environment 3 - Dropped From Vehicle 4 - Already in Road, But Fell From Vehicle 5 - Other 6 - Unknown	1 - Straight-Level 2 - Straight-Down Grade 3 - Straight-Up Grade 4 - Straight-Hillcrest 5 - Curve-Level 6 - Curve-Down G 7 - Curve-Up Grad 8 - Curve-Hillcrest	Unit 2	1 - None 2 - Shoulders Low 3 - Shoulders High 4 - Holes, Bumps, Etc. 5 - Other	1 - Asphalt 2 - Concrete 3 - Brick 4 - Unpaved 5 - Other	1 - Dry 2 - Wet 3 - Ice 4 - Snowy/Slushy 5 - Muddy 6 - Other	Yes Yes	1 - None 2 - Rocks 3 - Trees/Limbs 4 - Dirt	1 - Not Applicable 2 - Natural Environment 3 - Dropped From Vehicle 4 - Already in Road, But Fell From Vehicle 5 - Other 6 - Unknown	1 - Straight-Level 2 - Straight-Down Grade 3 - Straight-Up Grade 4 - Straight-Hillcrest 5 - Curve-Level 6 - Curve-Down G 7 - Curve-Up Grad 8 - Curve-Hillcrest																																																																		
Unit	Contributing Road Defects	Surface Construction	Condition	Accident In Or Related To Road Construction Zone?	Material in Roadway (Contributing)	Material Source	Character																																																																																													
Unit 1	1 - None 2 - Shoulders Low 3 - Shoulders High 4 - Holes, Bumps, Etc. 5 - Other	1 - Asphalt 2 - Concrete 3 - Brick 4 - Unpaved 5 - Other	1 - Dry 2 - Wet 3 - Ice 4 - Snowy/Slushy 5 - Muddy 6 - Other	Yes Yes	1 - None 2 - Rocks 3 - Trees/Limbs 4 - Dirt	1 - Not Applicable 2 - Natural Environment 3 - Dropped From Vehicle 4 - Already in Road, But Fell From Vehicle 5 - Other 6 - Unknown	1 - Straight-Level 2 - Straight-Down Grade 3 - Straight-Up Grade 4 - Straight-Hillcrest 5 - Curve-Level 6 - Curve-Down G 7 - Curve-Up Grad 8 - Curve-Hillcrest																																																																																													
Unit 2	1 - None 2 - Shoulders Low 3 - Shoulders High 4 - Holes, Bumps, Etc. 5 - Other	1 - Asphalt 2 - Concrete 3 - Brick 4 - Unpaved 5 - Other	1 - Dry 2 - Wet 3 - Ice 4 - Snowy/Slushy 5 - Muddy 6 - Other	Yes Yes	1 - None 2 - Rocks 3 - Trees/Limbs 4 - Dirt	1 - Not Applicable 2 - Natural Environment 3 - Dropped From Vehicle 4 - Already in Road, But Fell From Vehicle 5 - Other 6 - Unknown	1 - Straight-Level 2 - Straight-Down Grade 3 - Straight-Up Grade 4 - Straight-Hillcrest 5 - Curve-Level 6 - Curve-Down G 7 - Curve-Up Grad 8 - Curve-Hillcrest																																																																																													
<b>INVESTIGATION</b> <table border="1"> <thead> <tr> <th colspan="2">Light</th> <th colspan="2">Weather</th> <th colspan="2">Locale</th> <th colspan="2">Non-Vehicular Property Damage</th> <th colspan="2">Property Damage Description</th> </tr> </thead> <tbody> <tr> <td>1 - Daylight 2 - Dawn 3 - Dusk</td> <td>4 - Darkness—Road Not Lit 5 - Darkness—Road Lit</td> <td>1 - Clear 2 - Cloudy 3 - Rain 4 - Snow</td> <td>5 - Steel/Hail 6 - Crosswind 7 - Fog 8 - Other</td> <td>1 - Open Country 2 - Residential 3 - Shop's or Business 4 - Mfg. or Industrial</td> <td>5 - School 6 - Playground 8 - Other</td> <td>1 - None Visible 2 - Light</td> <td>3 - Moderate 4 - Severe</td> <td colspan="2">Concrete Guardrail Crash Cushion</td> </tr> <tr> <td colspan="2">Time Police Notified AM: 06:10 PM: 06:17</td> <td colspan="2">Time Police Arrived AM: 06:15 PM: 06:17</td> <td colspan="2">Time EMS Arrived AM: 06:15 PM: 06:17</td> <td colspan="2">Name of Photographer: Sgt. J. M. Bowman #431</td> <td colspan="2">Owner: State of Alabama (DOT) Address: 608 Chisholm St, Montgomery, AL 36111</td> </tr> <tr> <td colspan="2">Witness Full Name: Johnny Pollard</td> <td colspan="2">Address: 6356 Village Court, San Antonio, Texas</td> <td colspan="2">Telephone: (210) 684-0652</td> <td colspan="2">Witness Full Name: Michael Boozer</td> <td colspan="2">Address: 1155 Noremac Road, Montgomery, Alabama</td> </tr> <tr> <td colspan="2">Name of Investigating Officer: Corporal K.E. Green</td> <td colspan="2">Officer ID: 328</td> <td colspan="2">Agency ORI: 0030100</td> <td colspan="2">Name of Other Investigating Officers at Scene: Corporal R.A. Bradley</td> <td colspan="2">Officer ID: 081</td> </tr> <tr> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2">Agency ORI: 0030100</td> </tr> <tr> <td colspan="10">           The data on this report reflects my best knowledge, opinions and beliefs covering the accident, but no warrant is made as to the factual accuracy thereof.         </td> </tr> <tr> <td colspan="10">           Signature of Investigating Officer: <i>Spike</i> 228         </td> </tr> <tr> <td colspan="10">           Date: 04-11-2005         </td> </tr> </tbody> </table>											Light		Weather		Locale		Non-Vehicular Property Damage		Property Damage Description		1 - Daylight 2 - Dawn 3 - Dusk	4 - Darkness—Road Not Lit 5 - Darkness—Road Lit	1 - Clear 2 - Cloudy 3 - Rain 4 - Snow	5 - Steel/Hail 6 - Crosswind 7 - Fog 8 - Other	1 - Open Country 2 - Residential 3 - Shop's or Business 4 - Mfg. or Industrial	5 - School 6 - Playground 8 - Other	1 - None Visible 2 - Light	3 - Moderate 4 - Severe	Concrete Guardrail Crash Cushion		Time Police Notified AM: 06:10 PM: 06:17		Time Police Arrived AM: 06:15 PM: 06:17		Time EMS Arrived AM: 06:15 PM: 06:17		Name of Photographer: Sgt. J. M. Bowman #431		Owner: State of Alabama (DOT) Address: 608 Chisholm St, Montgomery, AL 36111		Witness Full Name: Johnny Pollard		Address: 6356 Village Court, San Antonio, Texas		Telephone: (210) 684-0652		Witness Full Name: Michael Boozer		Address: 1155 Noremac Road, Montgomery, Alabama		Name of Investigating Officer: Corporal K.E. Green		Officer ID: 328		Agency ORI: 0030100		Name of Other Investigating Officers at Scene: Corporal R.A. Bradley		Officer ID: 081										Agency ORI: 0030100		The data on this report reflects my best knowledge, opinions and beliefs covering the accident, but no warrant is made as to the factual accuracy thereof.										Signature of Investigating Officer: <i>Spike</i> 228										Date: 04-11-2005									
Light		Weather		Locale		Non-Vehicular Property Damage		Property Damage Description																																																																																												
1 - Daylight 2 - Dawn 3 - Dusk	4 - Darkness—Road Not Lit 5 - Darkness—Road Lit	1 - Clear 2 - Cloudy 3 - Rain 4 - Snow	5 - Steel/Hail 6 - Crosswind 7 - Fog 8 - Other	1 - Open Country 2 - Residential 3 - Shop's or Business 4 - Mfg. or Industrial	5 - School 6 - Playground 8 - Other	1 - None Visible 2 - Light	3 - Moderate 4 - Severe	Concrete Guardrail Crash Cushion																																																																																												
Time Police Notified AM: 06:10 PM: 06:17		Time Police Arrived AM: 06:15 PM: 06:17		Time EMS Arrived AM: 06:15 PM: 06:17		Name of Photographer: Sgt. J. M. Bowman #431		Owner: State of Alabama (DOT) Address: 608 Chisholm St, Montgomery, AL 36111																																																																																												
Witness Full Name: Johnny Pollard		Address: 6356 Village Court, San Antonio, Texas		Telephone: (210) 684-0652		Witness Full Name: Michael Boozer		Address: 1155 Noremac Road, Montgomery, Alabama																																																																																												
Name of Investigating Officer: Corporal K.E. Green		Officer ID: 328		Agency ORI: 0030100		Name of Other Investigating Officers at Scene: Corporal R.A. Bradley		Officer ID: 081																																																																																												
								Agency ORI: 0030100																																																																																												
The data on this report reflects my best knowledge, opinions and beliefs covering the accident, but no warrant is made as to the factual accuracy thereof.																																																																																																				
Signature of Investigating Officer: <i>Spike</i> 228																																																																																																				
Date: 04-11-2005																																																																																																				

SEE SHEET 2-4 OF 6

Diagram Not To Scale = (20 feet)	Location		06 05		A P M
Diagram Scale 1 Inch (10 feet)	MONTGOMERY				
Signature of Reporting Officer(s)	Officer ID	Reporting Police Agency DRI	DATE		
<i>CAIKE</i>	328	0030100	04	11	2005

## Definitions-

## Truck

A motor vehicle designed, used or maintained primarily for the transportation of property. For the purpose of this form the vehicle must also meet one of the following criteria:

- Have at least 6 tires on the ground, or
- Carry a Hazardous Material Placard.

## Bus

A motor vehicle providing seats for 16 or more persons including the driver and used primarily for the transportation of persons.

## Trailer

A non-power vehicle towed by a motor vehicle.


## Reportable Accident

A highway related incident normally investigated by a police officer and reported on a standard accident report form involving one or more trucks or buses (as defined here) which results in:


- One or more fatalities, or
- One or more non-fatal injuries requiring transportation for the purpose of obtaining immediate medical treatment, or
- One or more of the vehicles being removed from the scene as a result of disabling damage, or
- One or more vehicles requiring intervening assistance before proceeding under its own power.

## Typical Vehicle Silhouettes


1. Bus



2. Single unit truck - 2 axles / 6 tires



3. Single unit truck - 3 axles



4. Truck with trailer



5. Truck tractor (bobtail)



6. Tractor with semi-trailer




7. Tractor with double trailers



8. Tractor with triple trailers



## Typical Hazardous Material Placards



## UNIFORM TRA C ACCIDENT REPORT

LOCAL CASE NO.

Event # 70121

SHEET 5 OF 6 SHEET

AST No. 34 Rev. 4/88

## SUPPLEMENTAL SHEET

		Event #		70121		Unit No.		Seat Pos.		Injury Type		Age		Sex		Ejection		A		
ADDITIONAL ACCIDENT VICTIMS		3		Name	Address															
				Taken to	Taken by															
		4		Name	Address															
				Taken to	Taken by															
		5		Name	Address															
				Taken to	Taken by															
		6		Name	Address															
				Taken to	Taken by															
		7		Name	Address															
				Taken to	Taken by															
		8		Name	Address															
				Taken to	Taken by															
9		Name	Address																	
		Taken to	Taken by																	
10		Name	Address																	
		Taken to	Taken by																	
11		Name	Address																	
		Taken to	Taken by																	
12		Name	Address																	
		Taken to	Taken by																	
ADDITIONAL NARRATIVE SPACE		<b>DESCRIBE WHAT HAPPENED (Refer to vehicles by number)</b>																		
		<b>ADDITIONAL WITNESSES:</b>																		
		3. Jermale Ayers, 7140 Eastern Shores Road, Montgomery, AL (334)270-8990																		
		4. Michael Griggs 365 Law Road, Titus, AL (334)613-7788																		
		5. Stephen W. Hornsby 2395 Central Plank Road, Wetumpka, AL (334)514-1869																		
		6. Willie Rob Simmons 73 Cotton Blossom Road, Greenville, AL (334)382-7167																		
		7. Lisa Warr 2935 Highland Avenue, Montgomery, AL (334)262-3508																		

Alabama Uniform Traffic Accident Report  
Truck/Bus Supplemental SheetUnit No. 1  
(same as on main report)Sheet 6 of 6 Sheets

## General Instructions

Complete this form for each qualifying vehicle ONLY if the accident meets BOTH of the following criteria:

1. The accident involved a qualifying vehicle (truck with 6 or more tires or Haz/Mat placard, or a bus designed to carry 16 or more, including driver) and;
2. The accident resulted in at least one of the following: A. one or more fatalities B. one or more persons injured and taken from the scene for immediate medical attention, or C. one or more involved vehicles had to be towed from the scene as a result of disabling damage or had to receive assistance to leave.

## Screening Information

## Number of Qualifying Vehicles:

Trucks with 6 or more tires or Haz/Mat placard 1  
 Buses designed to carry 16 or more (including driver) 0

## Number of Persons:

Sustaining fatal injuries 2  
 Transported for immediate medical treatment 0

Number of vehicles towed from scene due to damage or provided assistance 2

## Vehicle Information

## Gross Vehicle Weight Rating (GVWR)

A. Truck, tractor or bus 13500  
 B. Trailer or trailers (total) 15000  
 Total GVWR for unit (A+B) 28500

## Hazardous Material Involvement

Did vehicle have a Haz/Mat placard Yes X No

If Yes, include following information from placard

A. Name or 4-digit number from diamond or box N/AB. The 1 -digit number from bottom of diamond N/AWas hazardous material released from THIS vehicle's cargo? Yes X NoTotal number of axles 5

## Vehicle Configuration (circle one number)

- 1 Bus 2 Single unit truck (2 axles/ 6 or more tires) 3 Single unit truck (3 or more axles)  
 4 Truck with trailer 5 Truck tractor only (bobtail) 6 Tractor with semi-trailer 7 Tractor with double trailers  
 8 Tractor with triple trailers 9 Unknown class heavy truck 10 Any other 4-tired vehicle

## Cargo Body Type (circle one number)

- 1 Bus 2 Van/enclosed box 3 Cargo tank 4 Flatbed 5 Dump  
 6 Concrete mixer 7 Auto transporter 8 Garbage/ refuse 9 Other

## Motor Carrier Information

NOTE: If NOT a motor carrier, enter NONE under Carrier Name, 0 for None under Carrier Identification Numbers, and go to Sequence Of Events Section

Carrier Name Benton Express Inc.Source (circle one number) 1 Vehicle side 2 Shipping papers 3 Driver 4 OtherCarrier mailing address (Street or P.O. Box) 2061 SCL DriveCity, State, Zip Jacksonville, Florida, 32209

Carrier Identification Numbers (None = 0)

US DOT 92694 ICC IVC 110410 STATE NO. STATE

## Sequence of Events

Note: for THIS vehicle - list up to four Event #1 15 Event #2 6 Event #3 10 Event #4 16EVENT  
CODES

- Non-Collision 1. Ran off road 2 Jackknife 3 Overturned (rollover) 4. Downhill runaway  
 5. Cargo loss or shift 6. Explosion or fire 7. Separation of units 8. Other non-collision  
 Collision With 9. Pedestrian 10. Non-parked vehicle 11. Parked vehicle 12. Train  
 13. Pedalcycle 14. Animal 15. Fixed object 16. Other object

Signature of Reporting Officer

Officer ID  
378Reporting Police Agency ORI  
0030100Date  
04-11-2005Time  
0605AM  
PM